

SPA INFORMATION

8.10.2021



DUE TO AN ISSUE WITH THE SPA TEMPERATURE SENSOR, THE SPA IS NOT HEATING AS NORMAL. ELITE POOLS IS SCHEDULED TO ADDRESS THIS ISSUE ASAP.

REDRHINO IS ALSO SCHEDULED TO REPAIR AN EXISTING LEAK ON AUGUST 18TH WEATHER PERMITTING, SUBJECT TO CHANGE.

THANK YOU FOR YOUR PATIENCE & UNDERSTANDING.